

Date: Monday, 4/23/2007 3:42:04 PM
User: Kim Johnston

Process Sheet

Customer	: CU-DAR001 Dart Helicopters Services	Drawing Name	: FOLDING STEP WELDMENT RH
Job Number	: 32024		
Estimate Number	: 10697		
P.O. Number	: <i>N/A</i>	Part Number	: D3388042
This Issue	: 4/23/2007 S.O. No. : <i>N/A</i>	Drawing Number	: D3388 REV A
Prsht Rev.	: NC	Project Number	: N/A
First Issue	: <i>N/A</i> Type : LARGE FAB ASSY	Drawing Revision	: A
Previous Run	: 27274	Material	: <i>N/A</i>
Written By	:	Due Date	: 5/1/2007
Checked & Approved By	: <i>07.04.23</i>	Qty:	1 Um: Each
Comment	: Est. B'05-06-10 Added Step 11 KJ/JLM Est Rev:C Revised Steps 06-06-14 JLM		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	D2622120C	Extrusion
-----	-----------	-----------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 1.0000 Each(s)

D2622-120C extrusion

Batch: *B30199*

FF 07-04-24 1

2.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1
-----	-------------	------------------------------



Comment: LARGE FABRICATION RESOURCE 1

CUT D2622-120C extrusion 85.15" long as per Dwg D3388

Deburr and bevel ends for welding

FF 07-04-24 1

3.0	D2734	206 Step Endplate
-----	-------	-------------------



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

206 Step Endplate

Pick:

Qty	Part Number	Description	Batch
2	D2734	End Cap	<i>B29340</i>

FF 07-04-25 1

4.0	D33872	Arm
-----	--------	-----



Comment: Qty.: 2.0000 Each(s)/Unit Total : 2.0000 Each(s)

Arm

Pick:

Qty	Part Number	Description	Batch
2	D3387-2	Arm	<i>B3020 32027</i>

FF 07-04-25 1

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 4/23/2007 3:42:04 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FOLDING STEP WELDMENT RH

Job Number: 32024

Part Number: D3388042

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

Weld arms and (1) end cap as per Dwg D3388.

Grind end cap welds flush

Dwg Rev: _____

A/R AL ROD Batch: M103317

B M102756

P.E. 07-04-25
P.E. 07-04-25

6.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

07/04/26 ①

7.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

07/04/26 ①

8.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

M.L. 07/04/26

9.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

P.E. 07-04-26

10.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Inspect for foreign objects as per QSI 024.

2-Weld last end cap as per Dwg D3388.

3-Grind end cap welds flush

Dwg Rev: A

A/R AL ROD Batch: M102756

P.E. 07-04-26 1
P.E. 07-04-26 1
P.E. 07-04-26 1

11.0

QC9

VISUAL WELDING INSPECTION



Comment: VISUAL WELDING INSPECTION

07/04/26 ①

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: PD Date: 07/04/30
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Monday, 4/23/2007 3:42:04 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FOLDING STEP WELDMENT RH

Job Number: 32024

Part Number: D3388042

Job Number:



Seq. #:

Machine Or Operation:

Description :

12.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

07/04/26 (1)

13.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Touch up Chemical Conversion Coat as per QSI 005 4.1

07/04/26 (1)

14.0

POWDER COATING

POWDER COATING



Comment: POWDER COATING

Powder Coat White Gloss (Ref: 4.3.5.1) as per QSI 005 4.3

07-04-26 (1)

15.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Wing Walk as per Dwg D3388 and QSI 005 4.4

07/04/27 (1)

16.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

MF 07-04-27 (1)

17.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

N/A

18.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

SD 07/04/27 (1)

19.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: G.A.

MF 07-04-27 (1)

20.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

07/04/30

Job Completion



07/04/30

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



RELEASED


05-03-11

UNDER REVIEW


From hays to chrys
OK, 06.10.26

DESIGN	IP	DRAWN BY	IP	DART AEROSPACE LTD
CHECKED	IP	APPROVED	IP	HAWKESBURY, ONTARIO, CANADA
DATE	05.01.20	TITLE	D3388	REV. A
A	05.01.20	STEP WELDMENT	NEW ISSUE	SHEET 1 OF 1
				SCALE
				NTS

NOTE: ALL WELDS SHALL BE 100% VISUALLY INSPECTED BY A QUALIFIED INSPECTOR PER DART QSI 004



TYPICAL STEP END DETAIL
NOT TO SCALE



D3388-041 LH STEP ASSEMBLY (SHOWN)
D3388-042 RH STEP ASSEMBLY (OPPOSITE)

- 1) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 2) WELD PER DART QSI 004 UNLESS OTHERWISE NOTED
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
POWDER COAT ENTIRE ASSEMBLY GLOSS WHITE (4.3.5.1) OR GREY SANDTEX (4.3.5.6)
OR BLACK SANDTEX (4.3.5.7) OR GREEN SANDTEX (4.3.5.8) PER DART QSI 005 4.3
BLACK ANTI-SKID PAINT PER DART QSI 005 4.4

ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE

WORK ORDER
NO. 32024

Copyright © 2005 by DART AEROSPACE LTD

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.